

# PRODUCT BULLETIN

SUBJECT: Obsolete TR3030S and replace with TR3030TS Models

## **PURPOSE:**

To advise the customer that the TR3030S models have been placed obsolete and replaced with the TR3030TS models.

#### 2 SCOPE:

Table 1 reviews the model replacement and effective dates.

Obsolete	Replace	Effective Date
3500001	3531001	Immediately
3530051	3531051	Immediately
3530801	3531801	Immediately
3530851	3531851	October 2010

Table 1

# **REASON:**

TR3030S are a severe service unit. In order to effectively use the severe service technology a breather tube must be present. The TR3030TS models are severe service and have the breather tube.

### **UNIT REPLACEMENT:**

The TR3030S (3530xxx) units will be replaced by TR3030TS (3531xxx) units, see Table 1.

Should you have any questions, please call your MGM Brakes Sales Representative or Corporate Sales Office at 1-800-527-1534.

FORM EF 3100 - 09/96 REV: 1 10-003